

## 623 MOTHERBOARD LAYOUT

We are utilizing a new motherboard. The 623 DMP motherboard has several layout changes that you must be aware of in order to replace the 531 or 630 motherboards. Please look over the layout drawing **BEFORE** attempting to connect the 623 motherboard to your unit. Failure to correctly connect your cables and wires to this board will cause damage to the motherboard or to other system components. Replacing major components in any electronic system requires **TRAINED PERSONELL** if you are unsure of how to proceed, please contact us at Coastal Amusements (732) 905 – 6662 before attempting repairs.

