



COASTAL AMUSEMENTS INC.


"...manufacturers & distributors of coin-op redemption games..."

SEA WOLF MAIN BOARD POWER ON PROCEDURES

Occasionally during shipment or other movement of the game, power to the motherboard may be interrupted, causing the "Bios" to become corrupted. Re-starting the motherboard is a simple task, as outlined below.


This procedure is required only when power to the motherboard has been interrupted, or the power supply is inoperative. Before you perform this procedure check to be sure that there is voltage to the power supply.

Symptom: Monitor displays "NO CABLE" and CPU fan and Power supply fan not operating.



ENLARGEMENT OF AREA

The picture above shows the pin configuration, located in the left corner on the main board. **Short the 2 green pins labeled "PWR SW" for 2 seconds and the board will re-boot and operate correctly.**



MOTHERBOARD

<http://www.coastalamusements.com/> and our Technical support line is open Monday thru Friday 7:00am to 4:30pm Eastern Standard Time (732)-905-6662

E-mail service@coastalamusements.com

1935 Swarthmore Ave, Lakewood, NJ. 08701 Phone: (732) 905-6662 Fax: (732) 905-6815

E-mail: service@coastalamusements.com

Website: <http://www.coastalamusements.com>